

25009 CR 561 - PO Box 609 Astatula, FL 34705

Building Inspections

Footing Monolithic Slab

Slab

Stem Wall

Bond Beam/ Lintel
Second Floor Lintel
Boof Shoothing Boof

Roof Sheathing Roof

Dry-in

Wall Sheathing

Wall Dry-in

Framing

Aluminum Track

Pre-siding dry-in/wire lath

Fire Rated Assembly Special Inspections

Insulation Roof Final

Building Final

Electrical Inspections

Underground Electrical

Ufer Ground

Tug Inspection

Electrical Rough-in Low Voltage

Rough-in Low Voltage Final

Electrical Final

Mechanical Inspections

Mechanical Rough-in/HVAC

Blower Door Test

Mechanical Final

Plumbing Inspections

Sewer Tie-in

Plumbing Rough-in

Underground Plumbing

Rough-in/Tub Set

Lawn Irrigation Water Service

Roof Drains Plumbing Rough-in

Plumbing Final

Well/Pump Final

Mobile Home Inspections

Mobile Home Setup

Building Final

Electrical Final

Mechanical Final

Plumbing Final

Natural/LP Gas Inspections

Gas Rough-in

Second Gas Rough-in

LP Tank Set

Gas Final

Retaining Wall Inspections

Retaining Wall Footing

Retaining Wall Lintel Steel

Retaining Wall Final

Re-Roofing Inspections

In Progress/Dry-in/Flashing

Re-Roof Final

Swimming Pool Inspections

Termite

Pool Enclosure Footing

Above Ground Spa Barrier Final

Retaining Wall Footing

Pool Retaining Wall Lintel Steel

Pool Retaining Wall Final

Pool Steel

Plumbing Rough-in/Main Drain Pool

Electrical Bond

Electrical Final

Pool Plumbing Final

Pool Final

Pool Enclosure Inspections

Enclosure Slab

Enclosure Footing

Enclose Monolithic Slab

Enclosure Final